



708 Heartland Trail
Suite 3000
Madison, WI 53717

608.826.3600 PHONE
608.826.3941 FAX

www.TRCSolutions.com

December 21, 2015

Mr. William J. Kowalski
Manager, Water and Waste Programs
Dairyland Power Cooperative
3200 East Avenue South
La Crosse, WI 54601

Subject: Alma Off-Site Disposal Facility - Annual Inspection by a Professional Engineer

Dear Mr. Kowalski:

This letter presents the results of the inspection of the Phase IV Alma Off-Site Disposal Facility located in Alma, Wisconsin. Prior to the inspection TRC reviewed the permitting documents, the weekly inspection forms, and the Fugitive Dust Control Plan. On November 9, 2015, Jonathan Hotstream, P.E., P.G. of TRC Environmental Corporation performed an on-site inspection of Dairyland Power Cooperative's (DPC) coal combustion residual landfill in the presence of Leif Tolokken of DPC. Attached to this letter are the inspection checklist and a photographic log to document the observed conditions.

Based on the documents reviewed and the site inspection, the landfill is designed, constructed, operated, and maintained consistent with good engineering practices. The site was being operated in a safe manner and there were no indications of structural weakness at the time of the inspection.

Sincerely,

TRC Environmental Corporation

Jonathan Hotstream, P.E., P.G.
Senior Engineer

Attachments: Landfill Inspection Checklist
Photographic Log

cc: Leif Tolokken - DPC
Todd Martin - TRC



Photographic Log

Client Name: Dairyland Power Cooperative		Site Location: Phase IV Off, Site Disposal	Project No.: 243332.0001
Photo No. 51	Date 11/9/2015		
Description View of working face of landfill and recently completed cell B1 in the foreground. CCR placement occurring at the top of the active filling area.			

1

Photo No. 61	Date 11/9/2015		
Description Water truck spraying recently placed CCR on the working face.			

1

1